

10

FIG.1







FIG.2






CROSS SPRING
SUPPORT POINT

FIG.3(a)



L-SHAPED SPRING
SUPPORT POINT

FIG.3(b)



ELASTIC
SUPPORT POINT

FIG.3(c)

FIG.4




FIG.5





FIG.6






FIG. 7(a)




FIG. 7(b)

FIG.8




FIG.9




FIG.10





FIG.11






FIG.12(a) FIG.12(b) FIG.12(c)

FIG.13





FIG.14






FIG. 15(a)




FIG. 15(b)





FIG.16(a)

FIG.16(b)

FIG.16(c)

FIG.17






FIG. 18(a)




FIG. 18(b)

FIG.19




FIG.20




FIG.21




FIG.22

